

RECEIVED
JAN 30 1991

DIVISION OF
OIL, GAS & MINING

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. GENERAL INFORMATION

1. Report Time Period: From (mo./yr.) 01/01/90 To (mo./yr.) 12/31/90
2. DOGM File Number (original notice): M / 049 / 006
3. Mine Name: Clinton Pit
4. Legal Description (Location of Lands Affected):
 1/4, 1/4, Section 8&9, Township 5S, Range 1W
 1/4, 1/4, Section , Township , Range
 1/4, 1/4, Section , Township , Range
5. Mineral(s) Mined: Clay
6. Name of Operator or Company: Interpace Industries, Inc.
7. Permanent Address: P.O. Box 12118
Ogden, Ut
84412

8. Company Representative (or designated operator):

Name: C.L. Patterson
Title: Plant Manager
Address: P.O. Box 12118, Ogden Ut 84412
Phone: (801) 782-7933

☒ Please check if any of the above information has changed since previous year.

II. MINING AND RECLAMATION

1. Was the mine active during the past year? Yes ☒ No ☐

2. If active, how much ore or mineral was mined? 45,300 tons

3. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, volume of material moved, and the acreage affected.

The North pit was lengthened and deepened. Average disturbed
increased by an estimated 1 1/2 acres. Volume removed was 95,000 yds.
of overburden.

4. Briefly describe the reclamation work performed during the past year. This description should include acreage reclaimed, methods employed, and an evaluation of the results.

65,000 yds of overburden from the north pit was used to backfill the
Lehi cut.

5. What was the total unreclaimed acreage at years end? 20⁺

6. Briefly summarize mining and reclamation planned for the upcoming year.

No activity planned

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. ADDITIONAL INFORMATION

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): C.L. Patterson

Title of Operator: Plant Manager

Signature of Operator: 

Date: January 28, 1990

jb
MNMR-AR